Question 36: With higher anticipated charge rates at the coker due to IMO, what are your best practices around defoamer application to minimize impact on hydrotreater catalyst life?

Print as PDF:

Tags

Delayed Coking

Year

2019